SYMBOL KEY

- LIGHT FIXTURE
- WALL MOUNTED SMOKE DETECTOR
- HEAT DETECTOR?
- WALL MOUNTED HEATER
- EXHAUST VENT
- PIPE

Adams Hall First Floor Ceiling Plan

Dean College Dormitory

Franklin, MA.

Reflected Ceiling Plan

Existing Conditions Surveys Inc.
475 Shawmut Ave, #2
Boston, MA 02118 USA
T 617.247.9181
F 617.248.0746
E info@existingconditions.com

The Most Accurate Existing Conditions Surveys and As-Built Surveys

No.	Date	Revision	By

No.	Date	Issued to	By

Title
Reflected Ceiling Plan

Date	01.15.2001
Scale	1"=2'-0"
Job No.	0102
Drawn By:	KJY

EX-4